

Annexure D

BUILDING SAFETY CERTIFICATE

No. 214/GAV/NBC/2025-26

Dated: 30/05/2025

It is certified that the existing building S.J.S. PUBLIC SCHOOL GURUBUXGANT (name of the building or premises) at BASIGAWAN, MAURAWAN ROAD, RAEBARELI.

..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	0+1	—	—	—	—	—

The building is owned/occupied by S.J.S. PUBLIC SCHOOL GURUBUXGANT (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of EXECUTIVE Engrs (RURAL) (Name of Department/ Govt.) on 30/05/2025 (date of inspection) in the presence of Mrs Praeti Singh (Principal) (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 30/05/2025 for a period of 29/05/2030 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 30/05/2025 at Raebareli by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : C. Rajendra Prasad

Designation : Executive Engrs

Name & Address of Department/ Office: Executive Engrs (Rural)

कार्यालय अधिशाषी अभियन्ता, ग्रामीण अभियन्त्रण विभाग, प्रखण्ड-रायबरेली।

पत्रांक- 214 / ग्रा०अ०वि० / जॉच - एन०बी०सी० / 2025-26, दिनांक - 30.05.2025

प्रमाण पत्र

विद्यालय का नाम - एस० जे०एस० पब्लिक स्कूल गुरुबक्सगंज रायबरेली।

प्रमाणित किया जाता है कि उपरोक्त विद्यालय का स्थलीय निरीक्षण अवर अभियन्ता द्वारा भारत की राष्ट्रीय भवन निर्माण संहिता 2016 में प्राविधानित सुरक्षा मानको की दृष्टि से दिनांक-28.05.2025 को सरंचित भवन का किया गया जिसमे भूतल पर 1 ऑफिस परिसर, 12 कक्षा कक्ष, एवं 02 लैब निर्मित है। व प्रथम तल पर 9 कक्षा कक्ष, एवं 01 पुस्तकालय निर्मित है। इस प्रकार कुल 24 कक्ष निर्मित है। विद्यालय में छात्र एवं छात्राओ के लिये पृथक पृथक पेयजल एवं शौचालय आदि की समुचित व्यवस्था हैं।

उक्त पूर्व निर्मित विद्यालय भवन का निर्माण कार्य प्रथम दृष्टया संतोषजनक प्रतीत होता है।

संलग्नक:- स्कूल नक्शा मूल रूप में ।

अधिशाषी अभियन्ता
ग्रामीण अभियन्त्रण / नगर पंचायत
प्रखण्ड-रायबरेली।